

10/30/01
10/001590
U.S. PTO

PATENT NUMBER and
ISSUE DATE

U.S. UTILITY Patent Application

APPL NUM 10001590	FILING DATE 10/30/2001	CLASS 347	SUBCLASS 16	GAU 2853	EXAMINER Lam Nguyen
**APPLICANTS: Jeffrey Barr; Jennifer Korngiebel; Tod Heiles; Steven Webb; Jeffrey Rutland;					
**CONTINUING DATA VERIFIED: NWE LN					
BEST AVAILABLE COPY					
** FOREIGN APPLICATIONS VERIFIED: NONE LN					
PG-PUB <input type="checkbox"/>		DO NOT PUBLISH <input type="checkbox"/>		RESCIND <input type="checkbox"/>	
Foreign priority claimed <input type="checkbox"/> yes <input checked="" type="checkbox"/> no 35 USC 119 conditions met <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Verified and Acknowledged Examiners's initials LN				ATTORNEY DOCKET NO 10014029-1	
TITLE : Method to correct for malfunctioning ink ejection elements in a single pass print mode <small>U.S. DEPT. OF COMM./PAT. & TM-PTO-436L (Rev. 12-94)</small>					

NOTICE OF ALLOWANCE MAILED		CLAIMS ALLOWED	
		Assistant Examiner	
ISSUE FEE		Total Claims	
Amount Due	Date Paid	Print Claim for O.G.	
		DRAWING	
		Sheets Drwg. Figs. Drwg. Print Fig.	
		Primary Examiner	
<input type="checkbox"/> TERMINAL DISCLAIMER		Application Examiner	
		PREPARED FOR ISSUE	
WARNING: The information disclosed herein may be restricted. Unauthorized disclosure may be prohibited by the United States Code Title 35, Sections 122, 181 and 368, Possession outside the U.S. Patent & Trademark Office is restricted to authorized employees and contractors only.			

FILED WITH:

☐ DISK (CRF)

☐ CD-ROM

(Attached in pocket on right inside flap)